T3NR7E 6 5
7 8

Found 1¼" PIPE 6" below SURFACE

FIELD BOOK
500-H

5-21-75
BROWN 41



T3NR8E Sec 29

FOUND Bolt & BRASS Washer
Stamped C.S. 2239

FIELD BOOK

SOC. H.

TULLY RD

5-21-75
BROWN 42

BUTLER
HOUSE



T3NR8E 29
32

Found Bolt & washer stamped
LS 2239

FIELD BOOK
500-1

TULLY RD

5-21-75
BROWN
BUTLER
HOUSE

43



T3NR8E 17
20

FOUND 2"x2" HUB FLUSH WITH ROAD SURFACE

FIELD BOOK

SOC. H.

5-21-85

TULLY'S HARNESS RDS

BUTLER 44

BROWN HOUSE



T3NR7E 1/4 cor. 20

FOUND Bolt & Brass Washer
LS 2235

FIELD BOOK
500-H

TULLY

5-21-75
BROWN 45

BLACK HOUSE



T3NR8E 65
78

Found Bolt & Brass washer
Stamped LS 2239

FIELD BOOK
600.H

SARGENT & TULLY 5-21-95
BROWN 46
BUTLER
HULSE



T4NR1E 17/16

FOUND BOLT & BRASS WASHER
STAMPED LS 2239

FIELD BOOK
500.H

DUSTIN

5-27-85
BROWN
BUTCH
HUGE



47

T4NR7E 20/21

Found 2" x 2" Hub

FIELD BOOK

50C F

DUSTIN

5-27-75
BROWN
BUTLER
HUSSE

48



T5NR7E 32/33

Found axle

FIELD BOOK

500-H

5-27-75

DUSTIN RD

BROWN 49

BUTLER



T4NR7E 7/8

Found 2" x 2" Hub

FIELD BOOK

50C-1

Kennefick RD

5-27-75

Brown 50

Butler

Hulse



T4NR7E 7/8

FOUND 2" X 2" HUD

FIELD BOOK

SOC. H.

KENNEFICK RD

5-27-75

ROUND 50



T4NR7E 33/34

Found Bolt & Brass washer
stamped LS2239

FIELD BOOK
ECC

Bruella Road

5-28-75
BROWN 51
BUTLER
HULSE



T4NR7E 28/27

Found Bolt & Brass washer
C.S 2'2 39

FIELD BOOK
EOC 1

5-28-75

Bruella Road

Brown
Butler
House

52

N

Road

PP

TP

36°

59°

59°

66°

Conc
Base
Tank
House

Bruella



T4NR7E 21/22

Found

FIELD BOOK

SOC H

Bruella

5-30-75
BROWN
BUTLER
HOUSE



T4NR7E 16/15

FOUND BOLT

FIELD BOOK

500-H

BUELLA ROAD

5-28-75

54



T4NR7E 4/3

Found 1 1/2" PIPE 18" deep brought TO SURFACE WITH 2"x2" HUB

FIELD BOOK

500-H

Bruella Road

5-28-15

BROWN 55

BUTLER

HULSE



T4NR7E 9/10

Found 5/8" IRON PIN 20" below Road SURFACE Brought TO SURFACE WITH 2"x2" HUB

FIELD BOOK

50C-1

5-28-75

BRUELLA ROAD

Brown Butler Hulse



T4NR8E 22 23
27 26

Found Bolt & washer stamped
LS 2239 IN MON BOX

FIELD BOOK
500-H

5-29-75
CLEMENTS & ACAMPO
BROWN 57
BUTLER
HULSE



T4NR7E ~~32~~ 35
~~T3NR8E~~ ~~5~~ 2
T3NR7E

Found 3/4" Rebar 8" below
Road surface

FIELD BOOK
500-H

5-30-75

Brandt Road

Brown 58
Butler
Hulse



T3NR6E

36

¼ Section Corner Fd ¾" ϕ Iron Pin, 40" below the Pavement, reset ⅝" ϕ Iron Rod 4" below the Pavement.

Old ties see BK 49, Pg 33

FIELD BOOK

500. H

MICKE Grove Rd (TIES) 59



T3NR6E

26	25
35	36

Section Corner Fd. Hub 2" X 2" TACK on Top

Old Ties Bk. 49X, Pg 12 - 1-18-63
Set ⅝" X 22" Bolt + Washer With Brass Washer in Concrete Stamped L.S. 2239 20' below Ground set 2" X 2" Hub + TACK on Top

FIELD BOOK
500-H



T3NR6E

26/35

¼ Section Corner Fd. ½ ϕ Bolt
+ WASHER flushed on pavement

FIELD BOOK

500. 1

TIES

HAM LANE

61



T3NR6E

35

¼ Section Corner Fd. R.R. Spike flushed on pavement.

FIELD BOOK

500-H

(TIES)

HAM LANE

62



T3NR5E | T3NR6E

13 | 18

24 | 19

Section Corner Fd. 2" □ Headed Iron bar 16" below the edge of pavement.

Old ties see BK 49 W, Pg 36
F.S. Vol. 5 Pg. 22

FIELD BOOK

500-H

(TIES)

Ray Road

63



T3NR5E T3NR6E

~~27~~ 17

12-17

¼ Section Corner Fd. R.R. Spike flushed on pavement.

FIELD BOOK

50C

(TIES)

500-H 64



T5NR7E T5NR8E

25 36 30

¼ Section Corner Fd. 1" ϕ
Iron bar 3" below The Ground.



T4NR7E

6/7

¼ Section Corner Fd. 1" Iron Pin 30" below the Pavement. Reset Hub 2" x 2" & TACK 2" below the pavement.

FIELD BOOK

EOC 1.



T4NR5E 24|19 T4NR6E
25|30

Section Corner Fd. S.J. Co.
Bolt + WASher (Brass) L.S. 2239
flushed on pavement

FIELD BOOK

ECC



T2NR8E
29 & 28

¼ Section Corners Fd. ½" Iron Pin flushed on pavement.

Old ties Refer: BK. 49M, Pg. 33
F.S. Vol. 5, Pg. 184
F.S. Vol. 7, Pg. 131

FIELD BOOK

LOC. F



T2NR8E

29|28
32|33

Section Corner Fd. 1" oIron bar, 8" below the Ground

Old ties Refer. BK. 49M, Pg. 33

F.S. Vol. 5, Pg. 138
F.S. Vol. 5, Pg. 33

FIELD BOOK
500-H



T2NR8E

29

¼ Section Corner Fd. ¾" Iron Pipe 10" below the Ground.

Old Ties Refer BK. 49 M Pg 34

FIELD BOOK

500-L



T1N R6E

3

¼ Section Corner Fd. 1" Iron Pipe Lowered 11" below the pavement.

FIELD BOOK

500-H



T2NR6E

6/5

4 Section Corner 3/4" Iron Pin with brass Washer L.S. 2239 S.J. Co.

Refer old ties. BK. 49M, Pg. 52

FIELD BOOK

500-H