

Location Map of Complaint for Sight Distance Obstruction - Southwest Corner of Peltier Road & Bender Road

San Joaquin County Geographic Information Systems
1810 East Hazelton Avenue, Stockton, California 95205

The information on this map is based on the most current information available to San Joaquin County Geographic Information Systems.
The County of San Joaquin does not warrant its accuracy, completeness, or suitability for any particular purpose.
The information on this map is not intended to replace engineering, financial or primary records research.

Reported Sight-Distance Obstruction at the Southwest Corner of Peltier and Bender Roads

APN 013-030-01 22353 Bender Road [Steve & Jacqueline West-property owners]

4/13/12

Centerline Peltier Rd.

Move post/sign 3' towards fence so, dist. from ℄ is a min. of 33'-0"

Close-up of Winery signs looking easterly

Photo taken from inside vehicle at stop bar location looking west along Peltier Road-Vehicles approaching on the east-bound lane

Reported Sight-Distance Obstruction at the Southwest Corner of Peltier and Bender Roads

APN 013-030-01 22353 Bender Road [Steve & Jacqueline West-property owners]

4/13/12

Photo taken from inside vehicle at stop bar location on Bender Road looking west along Peltier Road-Vehicle is approaching on the east-bound lane



Photo taken from inside vehicle at stop bar location at south intersection of Peltier Road and Bender Road looking east along Peltier Road