



Swimming Pool Official Inspection Report

Name of Facility: MOUNTAIN HOUSE HIGH SCHOOL	Date: 07/19/2023
Address: 1090 S CENTRAL PKWY, MOUNTAIN HOUSE 95391	
Owner/Operator: LAMMERSVILLE UNIFIED SCHOOL DIST	Telephone: (209) 836-7400
Program Element: 3616 - PUBLIC POOL/SPA - EXEMPT	
Inspection Type: ROUTINE INSPECTION - Operating Permit	

VIOLATIONS AND CORRECTIVE ACTIONS

Items listed on this report as violations do not meet the requirements set forth in the California Health and Safety Code section(s) 116043, 116040, & 116050. All violations must be corrected within specified timeframe. Violations that are classified as "MAJOR" pose an immediate threat to public health and must be corrected immediately or be subject to closure pursuant to California Code of Regulations (Title 22) section 65545.

#3 Safety Signs

OBSERVATIONS: REPEAT VIOLATION: The south and west entrance gates of the pool enclosure lack "Keep Closed" signage. Obtain and install a "Keep Closed" sign on the exterior side of each entrance gate. Correct by 2 weeks.

CALCODE DESCRIPTION: Pool operator shall keep safety signs well maintained. (CCR 65535) Safety signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise specified. Safety signs shall be affixed to a wall, pole, gate, or similar permanent structure in a location visible to all pool users, unless otherwise specified. (CBC 3120B)

#4 Safety Equipment

OBSERVATIONS: REPEAT VIOLATION: The life ring at the north side of the pool is not attached to a throw rope. Tie a throw rope (the length of this rope shall be at least half the width of the pool) to this life ring today.

The condition of the throw rope on the life ring on the south side of the pool is deteriorating. Obtain a new throw rope for this life ring by 1 week.

CALCODE DESCRIPTION: Safety equipment shall be provided, maintained, readily visible, and available for use. Pools shall have at minimum one 12 foot fixed-length rescue pole with a permanently attached body hook and one 17-inch life ring with an attached throw rope. Throw rope shall be of sufficient length to span the maximum width of the pool and shall be stored to prevent kinking or fouling. (CCR 65540)

#8 Pool and Deck Lighting

OBSERVATIONS: REPEAT VIOLATION: Over half of the pool lights are burned out. Repair/replace the burned out lights by 1 month.

CALCODE DESCRIPTION: Pools used at night shall be equipped with underwater light fixtures that provide complete illumination of the pool. When a pool is used at night, pool deck and emergency egress areas shall be provided with lighting. If underwater or deck lighting is not operational, the pool operator shall post a sign in 4-inch letters stating "NO USE OF POOL ALLOWED AFTER DARK" and shall secure the pool area and not permit any use of the pool after dark. (3115B)

OVERALL INSPECTION NOTES AND COMMENTS

OBSERVATIONS

Flow rate: 1,245 gpm Chlorine: 3.4 ppm Temp: ° F
 Cyanuric acid: <30 ppm pH: 7.2 Combined chlorine: 0.0 ppm

Swimming Pool Official Inspection Report

Facility Name and Address: [MOUNTAIN HOUSE HIGH SCHOOL, 1090 S CENTRAL PKWY, MOUNTAIN HOUSE 95391](#)

NOTES

Influent: 10

Effluent: 4

***REPEAT VIOLATIONS: Provide photos of correction for Items #3, 4, and 8 by 1 month (August 25, 2023)
E-mail or text to Kadeanne Linhares klinhares@sjgov.org / 209-616-3025 ***

No signature obtained

Report typed in the office 2:30p-2:47p

The person in charge is responsible for ensuring that the above mentioned facility is in compliance with all applicable sections of the California Health and Safety Code. If a reinspection is required, fees will be assessed at the current hourly rate.

Received by: _____ Name and Title: [discussed w/ Jesus Gil, Head Cust.](#)
EH Specialist: [KADEANNE LINHARES](#) Phone: [\(209\) 616-3025](#)